

DANVILLE STADIUM INSPECTION
DANVILLE, ILLINOIS



Project includes an inspection of the structural integrity of the Danville Stadium, built in 1946, including an in-depth inspection of the main timber structural framing members, a general evaluation of the secondary framing members and a complete inspection report detailing the type, extent and location of significant deterioration along with recommendations for repair.

Services Provided:

- Complete Structural Inspection
- Written Report of Findings
- Picture Documentation
- Repair Recommendations

This project reflects Firm
and Staff experience.



Excellence, Service, Integrity
www.esild.com